

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



FIG. 1
(CONVENTIONAL ART)









FIG. 3
(CONVENTIONAL ART)






FIG. 4
(CONVENTIONAL ART)




FIG. 5
(CONVENTIONAL ART)







FIG. 7
(CONVENTIONAL ART)




FIG

FIG. 1 is a perspective view of a multi-layered assembly 10. The assembly includes a base layer 30, a middle layer 40, and a top layer 45. The base layer 30 has rectangular features 31 and 32. The middle layer 40 has a series of rectangular features 41 and 42. The top layer 45 is positioned above the middle layer 40. A component 11b is shown at the bottom right, connected to the middle layer 40.



FIG. 9






FIG. 10




FIG. 11




FIG. 12




FIG. 13



FIG. 14

